
Did. 4.4/87 n.6.



August 28, 1987

Ms. Ruth Mancos U.S. EPA - Region V CERCLA Enforcement Section (5HE-12) 230 South Dearborn Street Chicago, IL 60604

Re: Sanitary Landfill Company Site

1855 Cardington Road

Montgomery County, Moraine, Ohio


Dear Ms. Mancos:

We have discovered two typing errors in the last two sentences of paragraph 3 of our letter to you dated August 20, 1987 on this subject. Attached for your files is a revised corrected version of the letter. We apologize for any inconvenience this may have caused.

Very truly yours,

President

Attachment



August 28, 1987

Ms. Ruth Mancos U.S. EPA - Region V CERCLA Enforcement Section (5HE-12) 230 South Dearborn Street Chicago, IL 60604

Re: Sanitary Landfill Company Site

1855 Cardington Road

Montgomery County, Moraine, Ohio

Dear Ms. Mancos:

This responds to EPA Region V's letter dated July 14, 1987 requesting information regarding the above-referenced landfill. Mr. Ken Tindall previously extended our deadline for responding to this letter through August 21.

As background information for you, The Hewitt Soap Company, Inc. is engaged exclusively in the manufacture of various bar soap and detergent bar cleansing products. These products are produced using simple manufacturing processes. Since the products are used by consumers for cleansing, the safety of the ingredients going into the products is of major concern to us.

Turning to your specific questions, we have not been able to locate any documents relating to the above-referenced site. Two of our current employees do recall following, on a few separate occasions, a dumpster truck containing solid waste from the Hewitt plant to a landfill which they believe was located on Cardington The trucks would have been operated by an independent hauler and not by Road. We believe the wastes transported on these occasions probably Hewitt employees. consisted of detergent bar products, pet soap, and bar wrappers and cartons. These materials are used by consumers and are not hazardous substances. We have no analytical results or material safety data sheets on these materials which may have been landfilled at Cardington Road. We do have formula cards for the various products we have manufactured in the past which show the designed formulas for the products.

With respect to our insurance coverage, Hewitt has been covered by numerous comprehensive general liability insurance policies in effect over the years with varying levels of insurance and deductibles. These policies do not expressly refer to hazardous substances or the above-referenced site. In our opinion, these policies insure against liabilities arising out of CERCLA or RCRA but, as you may know, the insurance industry is vigorously contesting this interpretation of comprehensive general liability policies in litigation throughout the United States. Our insurance documents are numerous and it would be burdensome to provide these materials. If you have specific questions about these policies or if you Ms. Ruth Mancos U.S. EPA - Region V August 28, 1987 Page Two

have a particular interest in a particular time period, please let me know and we will address those issues.

Please send all future letters on this matter to my attention.

Very truly yours,

Bruce L. Stichter

President

I hereby certify that the information contained herein is true and accurate to the best of my knowledge and belief.

Bruce L. Stichter

Sworn to and subscribed in my presence this $2 \frac{y}{2}$ day of August, 1987.

Notary Public

DOROTHY MIZERIK, Notary Public In and for the State of Ohio

My Commission Expires JUNE 27, 1991



Ms. Ruth Mancos U.S. EPA - Region V CERCLA Enforcement Section (5HE-12) 230 South Dearborn Street Chicago, IL 60604

1 Years of Excellence